

MIX 1

TUNE

MIX 2

PORTAMENTO

OCTAVE

4'
8'
16'

VC01 PW & PWM

LINK TO VC02 LINK TO VC03

OFF OFF

FREQUENCY VCO 1

VCO 1

DRIVER

LINK

OFF

SYNC

FREQUENCY VCO 2

VCO 2

DRIVER

LINK

OFF

SYNC

FREQUENCY VCO 2

VCO 3

DRIVER

LINK

OFF

SYNC

MIX 3

VIBRATO RATE

2Hz 3Hz 4Hz 5Hz 6Hz 8Hz 9Hz 10Hz 11Hz 12Hz

LINEAR DETUNE

PULSE WIDTH

10% 20% 30% 40% 60% 70% 80% 90%

LINEAR DETUNE

PULSE WIDTH

10% 20% 30% 40% 60% 70% 80% 90%

LINEAR DETUNE

PULSE WIDTH

10% 20% 30% 40% 60% 70% 80% 90%

VCA DRIVE

VIBRATO DEPTH

PWM

FM DEPTH

PWM

FM DEPTH

PWM

FM DEPTH

VCA CV 1V/OCT 1V/OCT VIB DEPTH

VCA IN VCA DRIVER OUT MIXER OUT

PWM 1V/OCT

SIN TRI

FM MIX1

SAW PULSE

PWM 1V/OCT

SIN TRI

FM MIX2

SAW PULSE

PWM 1V/OCT

SIN TRI

FM MIX3

SAW PULSE