

This additional BOM isn't approved

1 10n
4 4n7
4 10µ
3 6 pin header You'll need 6x female and 3x male
1 1N4148
1 2N3904
1 LM1458N
1 LM3900N
6 2N3906 matched ?
8 2N5087 mouser
1 100
9 220
4 100k
3 10k
7 12k1 12k 1% works too
3 13k
1 196k
1 1k
1 1k3
1 1k87* TEMPCO
1 220k
4 22M
1 270k
5 2k2
1 39k
1 4k7
1 56k
1 100k PTC10V trim pot

FOR PSU

2x 652-RLB0914-101KL

~~1x 80-SS26V-R100330 This won't fit! leave out~~ more infos later by DSL-man/LED-man

2x 5 pin MTA 156 Male and female 2x each (571-640445-5, 571-3-640426-5)

The main difference with the PSU is that except the 2 regulators everything is through hole

—

Author: LED-man/DSL-man

more infos here in next days <https://www.dsl-man.de/display/DSO/ARP+2600+Clone>

Date 15.Dec.2016